CAPSULE SUMMARY
BA- 869
D. Matthews House
1138 Corbett Road
Monkton, Baltimore County
1780 ca.
Private

The D. Matthews House was constructed in the small village of Piney Hill, which lay along York Road between Hereford and Philopolis. The house is representative of the many vernacular stone houses constructed throughout rural Baltimore County in the late 18th and 19th centuries. Although pre-1850 occupancy and ownership of the property is presently unknown, it was D. Matthews who resided in the dwelling in 1850. At that time, Piney Hill was only a cluster of dwellings at the intersection of Corbett and York Roads. Additionally, one of the York Road tollgates was placed in the community. Little growth occurred in the village over the following sixty years. The 1877 atlas indicates that Charles Matthews resided in the house in the late 1870s, while the Conrad family was the building's occupant in 1915. The D. Matthews House continues to serve as a single-family residence, and the surrounding landscape has retained its mid-19th century rural character through the late 1900s.

Exterior architectural evidence is supported by oral information that suggests that the D. Matthews House was initially constructed circa 1780 as a two-story, two-bay-wide dwelling and then enlarged circa 1850 by the construction of a two-and-a-half-story, three-bay-wide addition. This later construction established a new main block and relegated the older portion of the building to use as a wing. A vertical seam in the random rubble stone masonry is evident between the two sections. Interior end stone chimneys rise from the northeast side of the wood-shingled side gable roofs of the main block and wing. A one-story, circa 1910 porch that is four bays wide now spans the full façade, or southeast elevation, of the main block and wing. The porch has a half-hipped rood clad in standing seam metal supported by Tuscan columns that are spanned by a square-edged wood balustrade. The circa 1780 section is pierced by one sash-and-paneled single-leaf door with a one-light transom and two 6/6 windows on the first story and two 6/6 windows on the second story. The circa 1850 section features one sash-and-paneled single-leaf door with a two-light transom and two 6/6 windows on the first story.

Three 6/6 windows pierce the second story of this main block. All façade openings have square-edged wood surrounds and sills. Stone lintels surmount the second-story openings on the main block. Two wood frame additions, both of which are clad in board-and-batten siding, have been constructed on the rear of the building. Six historic dependencies, including a barn, stone silo, springhouse, smokehouse, drive-through corncrib, and carriage house are located on the property. Additionally, a circa 1980 garage is sited behind the house.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of F	Property	(indicate preferred na	ame)				
historic	D. Matthews Ho	ouse (preferred)					
other	Mary Glen Farm	1					
2. Location							
street and number	1138 Corbett Ro	oad				not for	publication
city, town	Monkton					vicinity	
county	Baltimore Coun	ty					
3. Owner of	Property	(give names and mailing	addresses	of all owner	s)		
name	Jeffrey Springer	, Trustee					
street and number	1138 Corbett Ro	oad			telephone	Not Ava	ilable
city, town	Monkton		state M	ID	zip code	21111	
Contril Contril Determ	buting Resource in buting Resource in nined Eligible for the nined Ineligible for ded by HABS/HAE c Structure Report	Additional Data National Register District Local Historic District he National Register/Marylan the National Register/Marylan Register/Marylan Register/Marylan Register/Marylan Register/Marylan Register/Marylan	d Register and Registe	er			
6. Classifica	tion						
Category district _X_building(s)structuresiteobject	Ownership —public _X_privateboth	government _ health care _	religio social transp work unkno	ation/culture on I portation in progress own ot/not in use		ng Nor	ncontributing L buildings sites structure objects L Total ting Resources the Inventory

_	_							
7.	D	26	CI	ri	n	ti	0	n
	\mathbf{r}	, ,			v	•1	v	

Inventory No. BA- 369

Condition

excellent	deteriorated
X good	ruins
fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Exterior architectural evidence is supported by oral information that suggests that the D. Matthews House was initially constructed circa 1780 as a two-story, two-bay-wide dwelling and then enlarged circa 1850 by the construction of a two-and-a-half-story, three-bay-wide addition. This later construction established a new main block and relegated the older portion of the building to use as a wing. A vertical seam in the random rubble stone masonry is evident between the two sections. Interior end stone chimneys rise from the northeast side of the wood-shingled side gable roofs of the main block and wing. A one-story, circa 1910 porch that is four bays wide now spans the full facade, or southeast elevation, of the main block and wing. The porch has a halfhipped rood clad in standing seam metal supported by Tuscan columns that are spanned by a square-edged wood balustrade. The circa 1780 section is pierced by one sash-and-paneled single-leaf door with a one-light transom and two 6/6 windows on the first story and two 6/6 windows on the second story. The circa 1850 section features one sash-and-paneled single-leaf door with a two-light transom and two 6/6 windows on the first story. Three 6/6 windows pierce the second story of this main block. All façade openings have squareedged wood surrounds and sills. Stone lintels surmount the second-story openings on the main block. Circa 1900, a two-story wood frame ell with a central interior stretcher bond chimney was constructed on the back of the main block and wing, and an addition to the ell was built circa 1990. An interior end stone chimney rises from the circa 1990 addition. Both wood frame additions are clad in board-and-batten siding.

Several historic dependencies are also located on the property. The circa 1850 barn is a two-and-a-half-story wood frame structure clad in flush vertical board siding with a side gable roof clad in standing seam metal. The building is banked into the hillside and features two flush-vertical-board sliding barn doors on the center of the three-bay-wide façade.

Beside the barn is a circa 1850 silo that is approximately forty feet tall and ten feet in diameter. Constructed of solid random rubble stone, the silo has a conical roof clad in sheet metal.

The circa 1850 springhouse is a one-story, one-bay-square building of solid random rubble stone construction with a wood-shingled front gable roof that hangs over the building's façade and is posted. The gable peak is clad in weatherboard. The façade is pierced by one flush-vertical-board single-leaf wood door with a hewn log surround.

The circa 1900 smokehouse is a one-story, one-bay-square stretcher bond brick building with a front gable roof. A paneled single-leaf door with a square-edged wood surround and jack-arched brick lintel pierces the façade.

Dating to circa 1900 is the two-story barn/drive-through corncrib. The wood frame building, which is clad in flush vertical board siding, features a front gable roof clad in corrugated sheet metal. A large open bay marks the center of the three-bay-wide building. The gable peak is pierced by a small window opening.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. BA- 869

Name D. Matthews House, 1138 Corbett Road, Monkton, Baltimore County Continuation Sheet

Number 7 Page 2

The circa 1900 carriage house has been extensively renovated and features a coursed rubble stone foundation that supports a wood frame structural system clad in board-and-batten siding. A brick veneer has been applied to the façade of the two-story building.

The circa 1980 garage appears to make use of an earlier stone foundation. This possibility was not verified at the time of the exterior survey. The three-bay-wide building features an asphalt-shingled side gable roof with board-and-batten siding in the gable ends.

8. Signific	ance			Inventory No. BA- 869
Period	Areas of Significance	Check and j	ustify below	
1600-1699 <u>X</u> 1700-1799 <u>X</u> 1800-1899 <u>X</u> 1900-1999 2000-	 X agriculture archeology X architecture art commerce communications community planning conservation 	economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	health/medicine industry invention landscape archit law literature maritime history military	philosophy politics/government recture religion science social history
Specific dates	1780 capresent		Architect/Builder	Unknown
Construction da	ates 1780 ca., 1850 ca., 1	900 ca., 1990 ca.		
Evaluation for:				
	National Register	N	Maryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The D. Matthews House was constructed 1780 in the small village of Piney Hill, which lay along York Road between Hereford and Philopolis. The house is representative of the many vernacular stone houses constructed throughout rural Baltimore County in the late 18th and 19th centuries. Although pre-1850 occupancy and ownership of the property is presently unknown, it was D. Matthews who resided in the dwelling in 1850. It might have been D. Matthews, then, who was responsible for the construction of the circa 1850 stone addition to the late 18th century house. At that time, Piney Hill was only a cluster of dwellings at the intersection of Corbett and York Roads. Additionally, one of the York Road tollgates was placed in the community. Little growth occurred in the village over the following sixty years. The 1877 atlas indicates that Charles Matthews resided in the house in the late 1870s, while the Conrad family was the building's occupant in 1915. Exterior architectural evidence suggests that the wood frame ell was constructed at this time. The D. Matthews House continues to serve as a single-family residence, and the surrounding landscape has retained its mid-19th century rural character through the late 1900s.

Vernacular buildings tend to have little to no stylistic detailing and are typically constructed by local builders with locally available tools and materials. Vernacular architecture accounts for the majority of the built environment and reflects the traditions of society, rather than the whims of the architect. Throughout Baltimore County, there are a number of vernacular stone houses from this period. Stone was readily available in the county, with both marble and granite quarries located throughout the region. Commonly, these random rubble stone dwellings are two stories in height, single-pile with side gable roofs. This continuity of form is a result of folk architecture and the reliance on constructing forms that had been built by the previous generation.

¹ J.C. Sidney, Map of the City and County of Baltimore, Maryland, from Original Surveys (Baltimore, MD: James M. Stephens, 1850). ² Atlas of Baltimore County, Maryland (Philadelphia, PA: G.M. Hopkins, 1877); see also Map of Baltimore County (Philadelphia, PA: G.W. Bromley, 1915).

³ Dell Upton and John Michael Vlach, editors, Common Places: Readings in American Vernacular Architecture, (Athens, GA: The University of Georgia Press, 1986), pp. xv-xvi.

9. Major Bibliographical References

Inventory No. BA - 869

Atlas of Baltimore County, Maryland. Philadelphia, PA: G. M. Hopkins, 1877.

Baltimore County Historic Inventory.

Brooks, Neal A. and Eric G. Rockel. A History of Baltimore County. Towson, MD: Friends of the Towson Library, Inc., 1979. Map of Baltimore County. Philadelphia, PA: G. W. Bromley, 1915.

Scharf, J. Thomas. History of Baltimore City and County From the Earliest Period to the Present Day: Including Biographical Sketches of Their Representative Men. Philadelphia, PA: Louis H. Everts, 1881. Reprinted by Higginson Book Company, Salem, MA.

Sidney, J. C. Map of the City and County of Baltimore, Maryland, from Original Surveys. Baltimore, MD: James M. Stephens, 1850.

10. Geographical Data

1.5 Acres		
Unknown		
Hereford	Quadrangle scale:	1:24,000
	Unknown	Unknown

Verbal boundary description and justification

Since its construction circa 1780, the D. Matthews House has been associated with the 19.50 acres of land known as tax parcel 179 of map 28 located in the Baltimore County Tax Assessor's office.

11. Form Prepared by


name/title	A. McDonald and A. Didden, Architectural Historians		
organization	EHT Traceries, Incorporated	date	May 29, 2001
street & number	1121 5th Street NW	telephone	202.393.1199
city or town	Washington	state	DC

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600





BA-0869
1138 CORBETT ROAD
MONKTON
BALTIMORE COUNTY, MO
TRALFRIES
3/2001
MD-SHRO
S CORNER



BA- 1869
1138 CORBETT ROAD
MONETON
BACTIMORE COUNTYIND
TRACTRIES
3/2001

MO-5480

SE CLEVATION



BA-0869
1138 LOCSETT ROAD
MONETON
BALTIMOLE COUNTY, MD
TEACERIES
3/200)
mD-SHPD

NE ELEVATION



1138 CORBETT ROAD MONETON BALTIMORT LOWNTY, MD TEALTELES 3/2001 mp-shoo W COLNEL

4 of 7



BA-0869

1138 CORBETT FORD

MONKTON

BALTIMOLE LOUNTY, MO

THA LELLES

3/2001

MD-SHPO

OUTBUILDINGS

3007



BA-0869
1138 CORSETT ROAD
MONETON
BALTIMORE COUNTY, MD
TRACERIES

CONCRIB

6 of 7

3/2001

MD-SHPO



BA-BLG 1138 CORBETT FOAD MONETON BAZTIMORE COUNTY, MD TRALECTES 3/2001 MO-SHPD

f7

SPRINGHOUSE

13A- 869

MARY GLEN FARM - 1850-1875 - North side of Corbett Road, 0.95 mile east of York Road. Stone, two-segment house in vernacular style, with gable roofing, two stories in each part. Three-bay main block; two bays in smaller and lower wing. Full-width front porch. Large flush chimney at east end of both sections. Good condition. Also red frame barn, stone springhouse with cantilevered roof over entrance, and early stone silo. Shown as Chas. Matthews house in 1877 atlas, as the Conrad house in 1898 and 1915 atlases. Owner: G. William Sattler.